# State of the state

# Work Order (Bid Form)

### **WORK ORDER INFORMATION**

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

**CLIENT INFORMATION** 

Client Name:

Client ID:

Alt. Client ID: 16016SW-1176

Address:

**AGENCY INFORMATION** 

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Phone: (731) 989-5111

Fax:

Email Address:

Company Name & License N	umber:
Contractor's Signature:	

### COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed

731-988-5821

Client Name:

Client ID: Alt. Client ID: 16016SW-1176

Work Order (Rid Form)

Work Order Name:

Report Run Ori: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0 Page 1 of 3

## Measures

	Measure 1 General Air Sealing				Components				
(	Comment				**				
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Repair hole on wall by D1 Door,Seal pipes under kitchen sinkSeal top of furnace closet	Each	1					
2	Labor	Labor	Hour						VIII. (1990)
3	Construction Materials/Hardwar e	Seal pipes under hall bath sink. Repair hole where old towel rack was and holes behind door	Each	1					
4	Labor	Labor	Each			-			
5	Construction Materials/Hardwar e	Repair water leak at end of tub, Seal wall in bedroom. Seal behind washer and dryer	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Caulk all windows on inside	Each	1		Í			
8	Labor	Labor	Hour						
0	ther Detail								
L				· Mr. communication					
			M	easure	Sub Total:		S	ub Total:	
And a second sec	Field Notes:			~					

Client Name:

Client ID:

Alt. Client ID: 16016SW-1176

Work Order (Bid Form)

Work Order Name:

Report Run Or: 5/28/2010

Page 2 of 3

Measure 2 DWH Pipe Insulation Comment				Componer	ıts		Inspecto		
oomment.		Estimated			Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DWH Pipe Insulation	Each	1						
2 Labor	Labor	Each	1					and the Evine of the seasons the season the	
Other Detail						l lamen measured	·		
		100 to 10						ri, - america de la composición del composición de la composición	
			Measur	e Sub Total:			Sub Total:		
Measure 3 CO	Monitor is Needed			Componen	ts		- I	nspecte	
Comment			Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Health and Safety     Items	CO monitor	Each	1		The second secon		AND THE RESERVE OF THE SECOND STATES OF THE SECOND		
2 Labor	Labor	Hour	1	And and an analysis of the second sec				n T	
Other Detail								ericalization for the second seconds	
		de manuel de la ma							
			leasure	Sub Total:		S	ub Total:		
Field Notes:									
					v				

Client Name: Client ID

Alt. Client ID: 16016SW-1176

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0 Page 3 of 3